



PREDATOR HELIOS 300















Pulsar Lighting Keyboard









Thunderbolt™ 4



Windows Desktop Apps¹⁰

2. Shared system memory may be allocated to support graphics, depending on system memory size and other factors. Actual system memory available to the operating system will be reduced by any memory used by the graphics solution and resources required by

Acer Care Center
 Acer Product Registration

- Specifications vary depending on model.
- Memory speed may vary, depending on the CPU, chipset or memory fitted.

One-year International Travelers Warranty (ITW)

Turbo Key

Planet9
PredatorSense

- Memory speed may vary, depending on the CPU, chipset or memory fitted.

 All brands and product names mentioned herein include trademarks of their respective companies and are used solely to describe or identify the products.

 Not all features indicated are supported on all SKUs

 1 GB is 1 billion bytes. Actual formatted capacity is less and may vary depending on preloaded materials and operating environment. Acer Recovery Management uses a portion of the stated hard disk capacity as dedicated backup space.

 Minor variations in system dimensions are possible due to the manufacturing process.

 Weight may vary depending on product configuration, vendor components, manufacturing variability, and selected options.

 Actual battery life may vary considerably by specifications, depending on product model, configuration, applications, power management settings, operating conditions, and features utilized. Performance variation also arises based on components in use, which in limited to the processor, RAM capacity, storage, display and resolution, etc.

 Bundled software may vary depending on hardware configuration, OS and regional availability.
- 10.

In a continuing effort to improve the quality of our products, information in this document is subject to change without notice. Images shown are only representations of some of the configurations available for this model. Availability may vary depending on region. As a phenomenon known to thin-film transistors (TFTs), liquid crystal displays (LCDs) commonly exhibit a small number of discoloration dots, as so-called "non-conforming pixels." This phenomenon is a limitation of TFT LCD technology, not a product defect, and as such is not covered by Acer's warranty.

© 2022. All rights reserved.

Microsoft and Windows are registered trademarks of Microsoft Corporation

Ultrabook, Celeron, Celeron Inside, Core Inside, Intel, Intel Logo, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside Logo, Intel Atom, Intel At

About Acer